
03 Mar 2014 (1215-0015 UT) OPERATOR: mcb
WEATHER INFO: Winds-> 3.2 mph @ 277, 18.5 C, 33.8% RH, 609.7 Torr, mostly clear

APA Recommissioning:

1. Nick, Kevin, Mike, Sean, Bob and Martin are on site.
2. We had no phone or internet all morning.
3. Bob Romeo of Composite Mirror Applications came by for ~1 hour to evaluate the repair of the BUS-to-Rx-Cabin radial-fin connections.
4. We thoroughly photo-documented the current condition of each of the feed legs.
5. We lifted the empty ARO rack into place on the platform.
6. We began refurbishing the Cryo Platform.
7. Sean greased the hoist swing arm, torqued the bolts to 50 ft-lbs, and installed the arm interlock.
8. The wx readings are garbage again. Hitting reset and cycling power on the A-to-D Interface box inside the wx station had no effect this time.

03 Mar 2014 (0015-1215 UT) OPERATOR:
WEATHER INFO: Winds-> 3.2 mph @ 277, 18.5 C, 33.8% RH, 609.7 Torr