

Power Routing

120VAC (White & Black)	- Power Supplies (3) - Focus Brake Relay - Fuse Holder - Fan Unit - Thermostat - On/Off Power Switch
+28Vdc (Blue)	- PWM Servo Amplifier
+12Vdc (Orange)	- Hard Drive - TA-100 Linear Amplifiers(2) - CPU
-12Vdc (Yellow)	- TA-100 Linear Amplifiers(2) - CPU
+5Vdc (Red)	- Hard Drive - CPU (2)
5V GND (Black)	-Hard Drive - CPU
+/-12V GND (Black)	- Hard Drive - CPU - TA-100 Linear Amplifiers
+/-15Vdc (Red/Green/Black)	- LVDTs and Focus Pot